

09757384 04801




FIG. 1




FIG. 2

09757384.041801




FIG. 3







FIG. 4



09757384.041804




FIG. 9

097573284-04401




FIG. 11a

095384-04301
T0840-48E45460




FIG. 116

097387 08E/5/60




Fig 12

FIG. 13

500




Fig. 13

This image is a high-contrast, black and white abstract scan. It features a dense, vertical band of dark, textured material, possibly a scan of a textured surface or a heavily degraded document page. The texture is grainy and noisy, with many small, dark specks and lines. The overall appearance is that of a low-quality, high-contrast scan of a physical object.




Fig. 14





Fig. 15



SYMBOLS	SINGLE PAYLINE	DOUBLE PAYLINE	TRIPLE PAYLINE 1000
7	10	100	32
TRIPLE BAR	8	16	8
DOUBLE BAR	2	4	4
BAR	1	2	2
BLANK	0	1	

Fig. 16

0957384.041801




Fig. 17

09757384-041801

Fig. 18




Fig 19

